B COOL Controls A/S

Consulting, Service and Spares for ships automation systems



Repair of Unisab II

Dear Sir

We do not have any new prints for the Unisab II.

However, we can repair your print(s) in very short time if required.

Further, we have two choices of "repair"

REPAIR:

You send the print for repair at our workshop and we repair and return within 5 days from receipt.

Repair price is:

Repair of Unisab II relay print is 1.638,00EUR Repair of Unisab II front cover is 1.054,00EUR Repair of Unisab II CPU print is 795,00EUR

REPLACEMENT:

We can send out a reconditioned print for you for replacement. When changed you will have to send the defective print return for us in order for us to repair and use for our next customer who choose replacement.

Replacement price is:

Reconditioned Unisab II relay print for replacement is 1.638,00EUR
Deposit for Unisab II relay print is 1.638,00EUR
Reconditioned Unisab II front cover for replacement is 1.054,00EUR
Deposit for Unisab II CPU print for replacement is 795,00EUR
Deposit for Unisab II CPU print is 795,00EUR

The deposit will off course be credited upon arrival of the defective parts.

When we do the replacement of the Unisab II relay print, we will need to know which REV (revision) you have of the relay print in order to deliver the correct relay print for you. You can find the REV "letter" as indicated on the picture on the next page.


CVR/VAT No. 36088079

E-MAIL: memac@bcool.as

B COOL Controls A/SConsulting, Service and Spares for ships automation systems



Packing/Freight will be approx. 60-90EUR depending on shipping destination.



CVR/VAT No. 36088079

E-MAIL: memac@bcool.as

B COOL Controls A/S

Consulting, Service and Spares for ships automation systems



Below you can see the layout of our Unisab II front cover:



We hope after you have read the above that you will choose to get your Unisab II print(s) repaired by our company.

You are also welcome to visit our home page at www.bcool.as where we also show which other electronic parts, we do repair.

Best regards

John Winther Director

CVR/VAT No. 36088079

E-MAIL: memac@bcool.as