

Repair of Unisab IIR

Dear Sir

We do not have any new prints for the Unisab IIR.

However, we can repair your print(s) in very short time if required.

Further, we have two choices of "repair"

REPAIR:

You send the print for repair at our workshop and we repair and return within 5 days from receipt.

Repair price is:

Repair of Unisab IIR relay print is 2.150,00EUR
Repair of Unisab IIR front cover is 1.383,00EUR
Repair of Unisab IIR CPU print is 1.043,00EUR

REPLACEMENT:

We can send out a reconditioned print for you for replacement. When changed you will have to send the defective print return for us in order for us to repair and use for our next customer who choose replacement.

Replacement price is:

Reconditioned Unisab IIR relay print for replacement is 2.150,00EUR
Deposit for Unisab IIR relay print is 2.150,00EUR
Reconditioned Unisab IIR front cover for replacement is 1.383,00EUR
Deposit for Unisab IIR front cover is 1.383,00EUR
Reconditioned Unisab IIR CPU print for replacement is 1.043,00EUR
Deposit for Unisab IIR CPU print is 1.043,00EUR

The deposit will off course be credited upon arrival of the defective parts.

Packing/Freight will be approx. 60-90EUR depending on shipping destination.

Unisab IIR relay print.



Below you can see the layout of our Unisab IIR front cover:



We hope after you have read the above that you will choose to get your Unisab IIR print(s) repaired by our company.

You are also welcome to visit our home page at www.bcool.as where we also show which other electronic parts, we do repair.

Best regards

John Winther
Director