


Alfa Laval Aalborg Boiler

Mission Boiler Control



Local Panel: Mission Controller in the grey box and front foil from Alfa Laval.



Power Panel: Mission Controller with Alfa Laval Foil.

Service rates 2026.

Item no.:	Description	EUR
	MISSION REPAIR	
1362-002M	Front cover for Mission incl. Display (Power panel only) (Our BCC frontcover)	1014
1316-002M	CPU print for MISSION repaired	593
1405-003M	MISSION Unicom card (COM IF) repaired	593
1608-002M	Mission I/O card (Piggy Back) repaired	593
1302-004M	MISSION relay print repaired	1.668
1310-001M	Complete MISSION controller repaired (Local or Power panel)	2.118

Repair:

- You can return your defective prints for check/repair.
- We can send out a repaired print so you can change the defective relay board in the same time you install the refurbished which will decrease your down time on the Boiler plant and then afterwards send the defective unit back to us.

Info:

- The most common error (98%) is that the relay print is worn out due to age/heat. If you have an error description we are able to tell you the problem with the controller in order for you to return only the defective prints or for us to send you the correct prints for replacement.

CHECK:

Item no.:	MISSION Check	EUR
	Front cover for MISSION incl. Display "Checked" (Power Panel)	203
	CPU print for MISSION "Checked"	203
	MISSION Unicom card (COM IF card) "Checked"	203
	MISSION relay print "Checked"	203

Check

We can check if your MISSION cards are defective or not. You will receive a report of the test result.
 If the test leads to a repair, we will not charge for the check only for the repair.